



Before you start using high reach machinery, always check for the presence of overhead electricity lines where you're working.

Ensure that everyone observes safe working practices where ever overhead lines are in the vicinity of your work area.

Coming into contact, or near contact, with overhead electricity lines can be fatal. Extra care should be taken when using high reach lifting equipment such as lorry cranes, fork lifts, teleporters, pole handlers, etc. (Refer to "*Code of Practice for Avoiding Danger from Overhead Electricity Lines*").

**IN CASE OF EMERGENCY CALL
1850 372 999**